











WILSON





WILSON TABLE ASSEMBLY INSTRUCTIONS

WILSON HARDWARE				
PACKAGE	ITEM #	SAMPLE	DESCRIPTION	QTY.
LEG/PANEL	H1		STUD BOLT 5/16" X 3-1/2"(M8X88mm)	4
	H2		FLAT WASHER 5/16" I.D.	8
	H3		HEX NUT 5/16" I.D.	8
CABINET/BEAM	H4		FLAT HEAD SCREW 1/4" X 1"(M6X25mm)	36
	H5		HEX HEAD CROSS BOLT 3/8" X 2-3/8"(M10X60mm)	4
	H6		HEX HEAD CROSS BOLT 3/8" X 1-3/4"(M10X45mm)	4
	H7		FLAT WASHER 3/8" I.D.	8
	H8		HEX HEAD CROSS BOLT 5/16" X 3-1/8"(M8X80mm)	16
RAIL/PACKET/SLATE	H9		FLAT WASHER 5/16" I.D.	16
	H10		FLAT HEAD SCREW 1/4" X 2-3/4"(M6X70mm)	16
	H11		STUD BOLT 5/16" X 5-1/2"(M8X140mm)	2
	H12		STUD BOLT 5/16" X 3-1/2"(M8X88mm)	4
	H13		FLAT WASHER 5/16" I.D.	12
	H14		HEX NUT 5/16" I.D.	12
	H15		FLAT HEAD HEX SOCKET BOLT 1/4" X 4-3/4"(M6X120mm)	62
	H16		FLAT HEAD SCREW 5# X 1/2"(M3X12mm)	24
	H17		FLAT HEAD SCREW 5# X 1/2"(M3X12mm)	36

WILSON HARDWARE				
PACKAGE	ITEM #	SAMPLE	DESCRIPTION	QTY.
	H18		FLAT HEAD SCREW 5# X 1/2"(M3X12mm)	28
	H19		HEX HEAD CROSS BOLT 3/8" X 2-3/8"(M10X60mm)	18
	H20		DOME WASHER 3/8" I.D.	18

WILSON COMPONENT PARTS				
PACKAGE	ITEM #	SAMPLE	DESCRIPTION	QTY.
LEG	1		LEG-A	2
	2		LEG-B	2
	3		METAL LEG PAD	2
BEAM	4		CABINET	1
	5		LONG WOODEN BLOCK	4
	6		SHORT WOODEN BLOCK	4
FRAME	7		LEFT SIDE APRON	2
	8		RIGHT SIDE APRON	2
	9		END APRON	2
TOP RAIL	10		TOP RAIL LEFT SIDE	2
	11		TOP RAIL RIGHT SIDE	2
	12		TOP RAIL END	2
POCKET	13		CORNER POCKET	4
	14		SIDE POCKET	2
	15		CORNER POCKET	4
	16		SIDE POCKET	2

WILSON COMPONENT PARTS				
PACKAGE	ITEM #	SAMPLE	DESCRIPTION	QTY.
SLATE	17		SLATE (LEFT)	1
	18		SLATE (CENTER)	1
	19		SLATE (RIGHT)	1
	20		ALUMINIUM ALLOY PIPE	32
	21		WOOD JOINT	4

WILSON INSTALLATION INSTRUCTIONS

FIG.1





FIG.2



WILSON INSTALLATION INSTRUCTIONS

FIG.3





FIG.4



WILSON INSTALLATION INSTRUCTIONS

FIG.5





FIG.6



WILSON INSTALLATION INSTRUCTIONS

FIG.7





FIG.8



WILSON INSTALLATION INSTRUCTIONS

FIG.9





FIG.10

Cut holes in cloth at rail both locations.



WILSON INSTALLATION INSTRUCTIONS

FIG.11






FIG.12



WILSON INSTALLATION INSTRUCTIONS

FIG.13



Finish

